

A) Precipitation /Rainfall

Name of Place/ Town Gauge Station	<u>Dated</u>	<u>Time</u>	<u>Rain fall Recorded (in mm)</u>
Mastung	06-01-2022	04:00 am to 07:00 pm	Traces (0.075 to 1.00 mm)
Mastung	06-01-2022	08:00 pm to 10:00 pm	1.75mm to 4.5 mm
Mastung	06-01-2022	10:00pm to 01:00 am	0.1 cm to 0.2 cm Snow at mountainous areas

B) Irrigation Schemes

Name of River	<u>Dated</u>	<u>Discharge of River (in Cusecs)</u>	<u>Name of Scheme Across/along the river</u>	<u>Status of Discharge</u>
Shireenab River	6/01/2022	0	Shireenab Flood Irrigation Scheme	Nil
Amach / Bahrm shahi	6/01/2022	0	Flood Channel Mastung Town	Nil

C) Water Storage Position.

S #	Name of Dam	District	Height (in ft:)	Catchment area (Sq: Mile)	Storage Capacity (A.FT)	Storage During recent Rainfall (A.Ft)	Damages If Any
1	Khad Kucha 1 Delay Action Dam.	Mastung	45	25.27	424	Nil	Nil
2	Duz Durg Delay Action Dam.	Mastung	42	58.02	331	Nil	Nil
3	Armach Delay Action Dam	Mastung	40	36.25	1558	Nil	Nil
4	Kanak Delay Action Dam	Mastung	20	59.55	6800	10	Nil
5	Toot Delay Action Dam	Mastung	30	10.49	238	Nil	Repair Required
6	Anjiri Delay Action Dam	Mastung	42	37.15	130	Nil	Repair Required
7	Sarband Delay Action Dam	Mastung	42	58.02	182	Nil	Repair Required
8	Nishpa Delay Action Dam	Mastung	50	33.66	377	Nil	Nil
9	Shaho Kushta Delay Action Dam	Mastung	50	81.92	178	15	Silted up
10	Kunger Delay Action Dam	Mastung	35	34.54	455	Nil	Nil
11	Hasil Check Dam	Mastung	30	3.24	76	Nil	Nil

12	Qamar Gaddi Delay Action Dam	Mastung	50	25.89	430	Nil	Repair Required
13	Thal Delay Action Dam	Mastung	40	28.48	1146	Nil	Nil
14	Les Degari Delay Action Dam	Mastung	55	13.46	484	Nil	Nil
15	Chiltan Delay Action Dam	Mastung	45	16.26	304	Nil	Repair required
16	Tori Kalan Delay Action Dam	Mastung	55	132.04	1001	Nil	Nil
17	Khadarini Delay Action Dam	Mastung	55	15.92	41	Nil	Nil
18	Isplinji Delay Action Dam	Mastung	40	81.92	197	Nil	Nil
19	Isplinji Delay Action Dam-II	Mastung	48	55.46	1748	Nil	Nil
20	Sikozai Delay Action Dam	Mastung	42	9.06	395	Nil	Nil
21	Khad Kucha Delay Action Dam-II.	Mastung	45	36.38	480	Nil	Repair Required
22	Kirdgap Storage Dam	Mastung	36	10.09	700	Nil	Nil
23	Dulay Check Dam	Mastung	30	5.13	251	Nil	Nil
24	Mukay Check Dam	Mastung	35	2.49	80	Nil	Nil
25	Zalo Check Dam	Mastung	37	5.2	257	Nil	Nil
26	Hilty Delay Action Dam	Mastung	47	7.68	559	Nil	Nil
27	Ali Deer Delay Action Dam	Mastung	36	8.07	412	Nil	Nil
28	Jalab Gandain Check Dam	Mastung	34	8.10	229	Nil	Nil

**EXECUTIVE ENGINEER
IRRIGATION DIVISION
MASTUNG**